



Tang for backstayblock

Cable stainless Ø6mm 7x19.
Length of cable without
fittings = 1750mm

Outhaul cable must be
changed every 3 years
as this cable effects the
safety of the boat.

Trampolins is recomended to
be replaced every 5 years
and or checked carefully and
Resew the seems again.

EasyLock for backstay.

Swing-Wing line :
10 Dyneema. 8mm
Must be changed every
3 years or when it starts
to be worn.

Easylock for
furling Genoa

Swing-Wing system